WATER QUALITY MEMORANDUM

Utah Coal Regulatory Program

January 6, 2011

TO:	Internal File				
THRU:	Daron Haddock, Permit Supervisor James D. Smith, Environmental Scientist				
FROM:	James D. Smith, Environmental Scientist				
RE:	2010 Third Quarter Water Monitoring, PacifiCorp. C/015/0019, Task ID #3624		Vilberg Mine,		
The Cottonwood/Wilberg Mine is currently idle. The water monitoring plan is described in Appendix A of Volume 9 of the MRP.					
There are no springs monitored at this site. The mine was sealed May 10, 2001, so in-mine monitoring sites TMA @ 32 and 2 nd S XC-11 are no longer accessible. WCWR1 at the Waste Rock Site is the only well monitored. The pond at the Cottonwood Fan Portal was reclaimed in 2002 so UPDES 22896-002 is no longer reported to DOGM or the Division of Water Quality. UT0022896-001 was the only UPDES outfall to discharge during the Third Quarter 2010.					
1. Were data submitted for all of the MRP required sites?					
Stream	ns				
The streams were mostly dry during the Third Quarter; the only streamflow reported was in September at site CCC1.					
Well		YES 🖂	NO 🗌		
UPDE	S	YES 🖂	NO 🗌		
DMRs are submitted in electronic format (Adobe). DMR data are submitted to the DOGM database as operational parameters, not as DMR parameters. UT0022896-001 was the only UPDES outfall to discharge during the Third Quarter 2010.					
2. Were all required parameters reported for each site?					
Stream	ns	YES 🖂	NO 🗌		

Page 2 C/015/0019 WG10-3 Task ID # 3624 January 6, 2011

	Well	YES 🖂	NO 🗌		
	UPDES	YES 🖂	NO 🗌		
	UT0022896-001 was the only UPDES outfall to discharge during the Third Quarter 2010.				
	3. Were any irregularities found in the data?				
not a p	Listed parameters were outside two standard deviations. An asterisk (*) indicates this is rameter required by the MRP.				
	Streams	YES 🗌	NO 🛚		
	Well	YES 🗌	NO 🛛		
	UPDES	YES 🖂	NO 🗌		
UT0022896-001 (WMD01) <u>September</u> : cation - anion balance. The ratio is -2.52%, well the ±5% criterion; however, the average value for this parameter is +1.4% and the negative value is outside the 2 standard-deviation range. [There is a long-term tree increasing bicarbonate and decreasing sulfate and chloride (see chart)].					
	4. On what date does the MRP require a five-year resample	iire a five-year resampling of baseline water data.			
The next permit renewal will be on 07/06/14. Baseline analyses were performed in 2001 and 200 and the next five-year baseline analyses will be in 2011.					
5. Based on your review, what further actions, if any, do you recommend?					
	No further action is required at this time.				
6. Does the Mine Operator need to submit more information to fulfill this quarter's monitoring requirements?					
	7. Follow-up from last quarter, if necessary.		na 🛛		
	8. Did the Mine Operator submit all missing and/or irregular YES There were no missing or irregular data in the Third Ouartee	NO 🗌	na 🖾		

